Seeburg


Service___

Select d'matic

Bulletin

CABINET VENTILATION

WARM WEATHER IS HERE AGAIN - -



MAKE SURE THE SCREEN IN THE BOTTOM OF THE SELECT-O-MATIC IS CLEAR AND THERE IS AT LEAST A 2-INCH SPACE BETWEEN THE BACK OF THE CABINET AND THE WALL